

- DISCONTINUED JET DRIVE KITS -

JOHNSON / EVINRUDE

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES	DRILL KIT NEEDED (5)
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"		
18-25	1959-1976	2	22	•	•	H18				
25	1977-1978	2	31.8	•	•	H25			1/2" Shaft	
25-28	1979-1989	2	31.8	•	•	H25-79			5/8" Shaft	
25-35	1955-1970	2	37.0-40.5	•	•	A25				
35-40	1958-1970	2	43.9	•	•	B35			5/16" Mtg. Bolts	
40	1971-1973	2	43.9	•	•	A40			5/8" Shaft	
40	1974-1989	2	43.9	•	•	A40-74			11/16" Shaft	
85-100	1969-1972	V4	92.6		•		M100		3/4" Shaft	•
115-125	1969-1972	V4	96.1		•		M125			
85	1973-1977	V4	92.6		•		M85-73		7/8" Shaft	•
115-135	1973-1977	V4	99.6		•		M135-73			
200	1991-2005	60° V6	158		•		60° R6P	60° R6PX		
200	1992-2005	90° V6	183.0 Only		•		R6-92P 7 5/8	R6-92PX 7 5/8		
225-250	1992-2005	90° V6	183.0-200.0		•		R6-92P 7 7/8	R6-92PX 7 7/8		
200	2005-2016	60° V6	158.2		•		60° R6P	60° R6PX	ETEC	
200	2005-2017	90° V6	200.0 (3.3L)		•		R6-92P 7 5/8	R6-92PX 7 5/8	ETEC	
225-250	2005-2017	90° V6	200.0 (3.3L)		•		R6-92P 7 7/8	R6-92PX 7 7/8	ETEC	

MERCURY / MARINER

35-40	1963-1989	2	33.3	•	•	F35	F35L		(3) (4)	•
35-50	1960-1964	4			•	C35			(1) (3)	•
40-50	1965-1997	4	43.9	•	•	E50	E50L		(2) (3) (4)	•
50-70	1972-1989	3	49.8		•	P65	P65L			•
65	1964-1971	4	62.4		•	G65	G65L			•
80	1969-1972	4	66.5		•	G80	G80L			•
75-85	1973-1986	4	66.6		•	G100	G100L			•
90-100	1965-1969	6	89.6		•	G100	G100L			•
90-150	1968-1987	6	99.8		•	G125	G125L			•
135-220	1976-2018	V6	121.2-153.0	•		S200	S200X			*

SUZUKI

40	1982	2	37.7	•	•	U2-2	U2L			
40	1983	2	37.7	•	•	U2-3	U3L			
50	1982-1983	2	44.1		•	T50	T50L			
50-65	1982-1984	2	48.7		•	T65	T65L			
55-65	1985-1997	3	54.4		•	T5-65	T5-65L			
75-85	1982-2000	3	73.0		•		T85			

CHRYSLER/FORCE

30-35	1967-1984	2	34.1		•	J35	J35L			
45-55	1967-1989	2	42.2-44.7		•	J50	J50L			
70-90	1969-1978	3	72.4		•	O85	O85L			
105-135	1966-1976	4	96.5-99.9		•	O120	O120L			

NOTES: •YES

(1) Up to serial #1450498

(2) From serial #1460499

(3) Long shafts not available for C35, E50 kits prior to serial #2097480 and F35 kits prior to serial #2155761. Instead use the short shaft with shaft extension #256

(4) Tiller requires use of Gate Shift Assembly, 969 Short or 970 Long

(5) Spotfacer & Drill kit needed to mount jet to motor. Return after use (except dealers) for refund.

(*) Drill kit needed on older models.

Outboard Jets

DIVISION OF
SPECIALTY MFG. CO.
2035 EDISON AVENUE
SAN LEANDRO, CA 94577
(510) 562-6049 • FAX (510) 562-0309
www.outboardjets.com