

JET DRIVE KITS

2021-2022

HONDA 4 STROKE MOTORS

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES	PRICE
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"		
40-50	1992-2003	3	49.3		•	AI45R	AI45LR		2, 5	2281.50
				•		AI45M	AI45LM		1, 2, 5	2281.50
40-50	2004-Present	3	49.3	•		AI50C	AIL50C		1, 2, 5, 7	2281.50
60	2010-Present	3	60.9		•		BE60			2793.47
				•			BEC60		1	2817.06
75-90	1996-2006	4	97.0	•	•		AN90		3, 4	2817.06
75	2007-Present	4	91.5	•	•		BE75		6	2817.06
90	2007-Present	4	91.5	•	•		BE90		6	2817.06
115-130	1998-2010	4	137.0		•		AN130		4	2843.02
115	2011-Present	4	144.0		•		AY	AYX		2952.75
135-150	2004-Present	4	144.0		•		AY	AYX		2952.75
200-225	2002-Present	V6	212.0		•		AV 7 5/8	AVX 7 5/8		3155.63
225-250	2002-Present	V6	212.0		•		AV 7 7/8	AVX 7 7/8	8	3221.70

NOTES: •YES

(1) Includes shift cable assembly or shift rod for tiller steering.

(2) Requires a factory gear set change at the base of crankshaft to operate with a Jet Drive.

This requires purchase of Honda Parts #23411-ZW4-E50, #90202-PB6-010, #23437-ZW4-E50, #11381-ZV5-004 and #23162-ZV5-024. We strongly recommend that a certified Honda Marine Mechanic perform this service.

Only 50HP Honda factory motors, supplied without a gear case, have the Jet Drive gear set installed.

(3) For Tiller Steering, requires cable assy #31 through 2003, #1829 starting in 2004 (long tiller handle).

(4) Includes water pump kit.

(5) Add \$180.00 for 6 1/8 stainless steel impeller upgrade, #1737.

(6) Requires shift cable 1829 for Tiller Steering

(7) Long tiller handle starting in 2004, shift cable assy, #1828.

(8) Uses 7 7/8 impeller and liner in place of 7 5/8 impeller and liner.