

- DISCONTINUED JET DRIVE KITS -

JOHNSON / EVINRUDE

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES	DRILL KIT NEEDED (5)
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"		
18-25	1959-1976	2	22	•	•	H18				
25	1977-1978	2	31.8	•	•	H25			1/2" Shaft	
25-28	1979-1989	2	31.8	•	•	H25-79			5/8" Shaft	
25-35	1955-1970	2	37.0-40.5	•	•	A25				
35-40	1958-1970	2	43.9	•	•	B35			5/16" Mtg. Bolts	
40	1971-1973	2	43.9	•	•	A40			5/8" Shaft	
40	1974-1989	2	43.9	•	•	A40-74			11/16" Shaft	
85-100	1969-1972	V4	92.6		•		M100		3/4" Shaft	•
115-125	1969-1972	V4	96.1		•		M125			
85	1973-1977	V4	92.6		•		M85-73		7/8" Shaft	•
115-135	1973-1977	V4	99.6		•		M135-73			

MERCURY / MARINER

35-40	1963-1989	2	33.3	•	•	F35	F35L		(3) (4)	•
35-50	1960-1964	4			•	C35			(1) (3)	•
45-50	1965-1989	4	43.9	•	•	E50	E50L		(2) (3) (4)	•
50-70	1972-1989	3	49.8		•	P65	P65L			•
65	1964-1971	4	62.4		•	G65	G65L			•
80	1969-1972	4	66.5		•	G80	G80L			•
75-85	1973-1986	4	66.6		•	G100	G100L			•
90-100	1965-1969	6	89.6		•	G100	G100L			•
90-150	1968-1987	6	99.8		•	G125	G125L			•

SUZUKI

40	1982	2	37.7	•	•	U2-2	U2L			
40	1983	2	37.7	•	•	U2-3	U3L			

CHRYSLER/FORCE

30-35	1967-1984	2	34.1		•	J35	J35L			
45-55	1967-1989	2	42.2-44.7		•	J50	J50L			
70-90	1969-1978	3	72.4		•	O85	O85L			
105-135	1966-1976	4	96.5-99.9		•	O120	O120L			

NOTES: •YES

(1) Up to serial #1450498

(2) From serial #1460499

(3) Long shafts not available for C35, E50 kits prior to serial #2097480 and F35 kits prior to serial #2155761. Instead use the short shaft with shaft extension #256

(4) Tiller requires use of Gate Shift Assembly, 969 Short or 970 Long

(5) Spottfacer & Drill kit needed to mount jet to motor. Return after use (except dealers) for refund.

Outboard Jets

DIVISION OF
SPECIALTY MFG. CO.
2035 EDISON AVENUE
SAN LEANDRO, CA 94577
(510) 562-6049 • FAX (510) 562-0309
www.outboardjets.com