

JET DRIVE KITS

2019-2020

HONDA 4 STROKE MOTORS

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES	PRICE
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"		
40-50	1992-2003	3	49.3		•	AI45R	AI45LR		7	2132.24
				•		AI45M	AI45LM		1, 7	2132.24
40-50	2004-Present	3	49.3	•		AI50C	AI50C		1, 7, 8	2132.24
60	2010-Present	3	60.9		•		BE60			2610.72
				•			BEC60		1	2632.77
75-90	1996-2006	4	97.0	•	•		AN90		3, 4	2632.77
75	2007-Present	4	91.5	•	•		BE75		3	2632.77
90	2007-Present	4	91.5	•	•		BE90		3	2632.77
115-130	1998-2010	4	137.0		•		AN130		4	2657.03
115	2011-Present	4	144.0		•		AY	AYX		2759.58
135-150	2004-Present	4	144.0		•		AY	AYX		2759.58
200-225	2002-Present	V6	212.0		•		AV 7 5/8	AVX 7 5/8	11	2949.19
225-250	2002-Present	V6	212.0		•		AV 7 7/8	AVX 7 7/8	11	3010.93

NOTES: •YES

- (1) Includes shift cable assembly or shift rod for tiller steering.
- (2) Requires a factory gear set change at the base of crankshaft to operate with a Jet Drive.
Only 50HP Honda factory motors, supplied without a gear case, have the Jet Drive gear set installed.
- (3) For Tiller Steering, requires cable assy #31 through 2003, #1829 starting in 2004 (long tiller handle).
- (4) Includes water pump kit.
- (7) Add \$160.00 for 6 1/8 stainless steel impeller upgrade, #1737.
- (8) Long tiller handle starting in 2004, shift cable assy, #1828.
- (11) Uses 7 7/8 impeller and liner in place of 7 5/8 impeller and liner.