

JET DRIVE KITS

2017

YAMAHA 2 STROKE MOTORS

HP	YEAR	NO. CYL	DISPL. CU. IN.	STEERING		MOTOR SHAFT LENGTH			NOTES	PRICE
				TILLER HANDLE	REMOTE CONTROL	15"	20"	25"		
25	1987-Present	2	24.1	•		BA	BAL		2,16	1811.00
25-30	1987-2002	3	30.27	•	•	Z30R	Z30LR			1862.00
				•		Z30M	Z30LM		2	1883.00
40-50	1983-1994	3	42.6	•	•	ZSR	ZLR		8	1883.00
				•		ZSM	ZLM		8	1883.00
40-50	1995-Present	3	42.6	•	•	AJSR	AJLR		8	1883.00
				•		AJSM	AJLM		2, 8, 11	1934.00
60-70	1983-2003	3	51.8	•	•		Y70		9	2120.00
60-70	2004-Present	3	51.8	•	•		Y70-04		9, 10	2120.00
75-90	1983-Present	3	69.6		•		Y90			2325.00
115-130	1983-Present	V4	105.5		•		AA4			2377.00
150-225	1983-Present	V6	158.4		•		AA6	AA6X	5	2433.00
175-225	1991-Present	V6	158.4		•		AA6P	AA6PX	5, 7	2607.00
225	1991-Present	V6	158.4		•		AA6P 7 7/8	AA6PX 7 7/8	5, 7, 17	2663.00
200-250	1998-Present	V6	191.0-204.0		•		AQ	AQX	4	2675.00
225-250	1998-Present	V6	191.0-204.0		•		AQ 7 7/8	AQX 7 7/8	4, 17	2731.00

YAMAHA 4 STROKE MOTORS

F30	2014-Present	3	45.6 (747 cc)	•	•	AJSR-43	AJLR-43		1, 8,	1892.00
				•		AJSM-43	AJLM-43		1,2,8,11,12,14	1939.00
F40	1999-Present	3	45.6 (747 cc)	•	•	AJSR-43	AJLR-43		1, 8,	1892.00
				•		AJSM-43	AJLM-43		1,2,8,11,12,14	1939.00
F50	1995-2005	4	57.0	•	•		AJL-44 14T		1, 6, 8	1883.00
				•			AJCL-44 14T		1,2,6,8,11	1934.00
F50-60	2002-Present	4	60.8	•	•		AJL-44 16T		1, 8	1883.00
				•			AJCL-44 16T		1, 2, 8, 11	1934.00
F70	2010-Present	4	60.8	•	•		BL		1, 8	1930.00
				•			BLC		1, 2, 8	1980.00
F75-100	1998-Present	4	97.4	•	•		Y100-4	Y100-4X	1	2349.00
				•			Y100C-4	Y100C-4X	1, 2, 11	2398.00
F115 -A	2000-2013	4	106.2		•		AA115-4	AA115-4X	1, 11	2398.00
F115 -B	2014-Present	4	111.8		•		AA115-4-14	AA115-4-14X	1, 11, 19	2398.00
F150	2003-Present	4	164.8		•		AW	AWX	15	2503.00
F150-200	2014-Present	4	170 (2.8 L)		•		AW 2.8L	AWX 2.8L	19	2503.00
F200	2013-Present	4	170 (2.8 L)		•		AQ 2.8L	AQX 2.8L	4, 19	2675.00
F200-225	2002-Present	V6	204.6 (3.3 L)		•		AQ 7 5/8	AQX 7 5/8	4	2675.00
F250	2002-Present	V6	204.6 (3.3 L)		•			AQX 7 7/8	4	2675.00
VF200-225	2011-Present	V6	256 (4.2 L)		•		AQ SHO 7 5/8			2675.00
VF225-250	2011-Present	V6	256 (4.2 L)		•		AQ SHO 7 7/8		17	2731.00
VF250	2011-2015	V6	256 (4.2 L)		•			AQX SHO 7 7/8	17	2731.00
VF250	2015-Present	V6	256 (4.2 L)		•			BUX SHO 7 7/8	17	2731.00

JET DRIVE KITS

2017

NOTES: ●YES

- (1) 4 stroke motors need pressure relief hole in cooling pump housing. Instructions in kit.
- (2) Includes shift cable assembly or shift rod for tiller steering.
- (4) Includes neutral cable assy #1566.3
- (5) Specify if for HPDI – add neutral cable #1566.3.
- (6) Driveshaft change year 2000. Specify spline, 14 or 16 teeth.
- (7) Heavier load capability then AA6 series.
- (8) Add \$160.00 for 6 1/8 stainless steel impeller upgrade, #1737.
- (9) Driveshaft change in 60-70HP 2 stroke motors starting in 2004.
- (10) Tiller handle model requires shift cable #1383.
- (11) Tiller handle change in 2006 - specify #1856 or #1857 shift cable assy for tiller steering.
- (12) 2006 tiller handle, rope start motor requires neutral start cable #1566.3.
- (13) Starting 2006, shift cable assy #1954 replaces shift rod assy #1295.
- (14) Starting 2009, F40 Yamaha EFI motor requires shift guide #2042, not #1651
- (15) AW tiller steering requires neutral cable 547.2 (5 ft.)
- (16) Will not fit C series motors.
- (17) Uses 7 7/8 impeller and liner in place of 7 5/8 impeller and liner.
- (18) Starting 2006, shift cable assy #2185 replaces shift cable assy #1954.
- (19) Includes VF SHO motors.